




## **TERMATRAC TEST REPORT** **SUPPLEMENT TO TIMBER PEST REPORT**

This Termatrac® test report is a supplementary report only, which MUST be read in conjunction with the full timber pest report. This report cannot be relied upon without the full timber pest report and is only a record of the test findings

<b>Tests were carried out by:</b>	Smart Cookie
<b>Date:</b>	July 17, 2014
<b>Timber Pest Report Number:</b>	1
<b>Report for building at:</b>	14/65 Christensen Rd, Stapylton
<b>Report requested by:</b>	Ron Burgundy

# 1 Garage

## 1.1 Radar Scan



**Scan Location:** Interior/Ground/Garage


**Termatrac device was:** On a solid platform

**Termatrac device position:** Flush against surface

**Damage Visible:** Yes

Privacy door jamb


## 1.2 Radar Scan



**Scan Location:** Interior/Garage  
**Termatrac device was:** On a solid platform  
**Termatrac device position:** Flush against surface  
**Damage Visible:** Yes


Privacy door eastern jamb

### 1.3 Radar Scan



**Scan Location:** Interior/Garage  
**Termatrac device was:** On a solid platform  
**Termatrac device position:** Flush against surface  
**Damage Visible:** Yes

## 1.4 Radar Scan



**Scan Location:** Interior/Garage  
**Termtac device was:** On a solid platform  
**Termtac device position:** Flush against surface  
**Damage Visible:** Yes

## 1.5 Garage Summary

Coptotermes Spp. located within garage molding timbers (skirtings, architraves, door jamb). The damage is wide spread and an entrance point has been located on the northern wall. In this instance the Termites have entered over the slab edge and Kordon sheeting which was bridged by a cardboard storage box.

**Insect Type:** Subterranean Termite  
**Test was:** Inconclusive\*

*\*Note: At the time of the Termtac testing it was impossible to confirm insect activity. It is advisable to reinspect and test this area at a different time of day or a later date or perform a more invasive inspection.*